



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

date	Sample Location	pH	Alk	PO4	TEMP	Y/N
------	-----------------	----	-----	-----	------	-----

4/1/22	West Hall	7.48			13.9 ^c	Y
4/1/22	Rm # 15	7.37			12.7 ^f	Y
4/1/22	West Hall	7.4			15.9 ^c	Y
4/1/22	Rm # 15	7.13			12.4 ^f	Y
4/29/22	West Hall	7.5			15.1 ^c	Y
4/29/22	Rm # 15	7.4			13.2 ^c	Y

<Has sample met the minimum(s)?

County: Clackamas Agency: CLACKAMA

DISTRIBUTION

PWS ID 4194670

OREGON TRAIL SD - BORING MID SCH

Sample Period: 4/22
Month/Year

Sample Frequency: Every 12 months

Distribution Samples required: 1

Number of excursions during this Sample Period = 0

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Lance Brooks

Signature: Lance Brooks

Date: 4/29/22

(N = No = Excursion) Total N's 0

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>