

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Dele					(EM)		
田淵	Sample Location	рН	Alk.	PO4	Other	Y/N	<has sample<="" td=""></has>
1/10/5	WeSt Hall	7,4	ALUMANA PARA		19.10	Y	met the minimum(s)? DISTRIBUTION
1/ola	Rm # 15	715			14.3	Y	
	ı						PWS ID 4194670
11/2/10	West Hall	7.4			1190	У	
1/2/12	Pm # 15	7.5			9.76	r	OREGON TRAIL SD - BORING MID SCH
							11/27
\vdash							Sample Period: 1//22 Month/Year
	•		\dashv			*******	Sample Frequency: Every 12 months
							Distribution Samples required: 1
							Number of excursions during this Sample Period =
-							(Number of locations when any WQP
				\dashv		_	was less than the minimum.)
	-					,	Note: Entry Point and Distribution
							Note: Entry Point and Distribution Excursions are cumulative. Add Entry
							Point and Distribution Excursions to get total for sample period.
·			-			_	
							1.2.3.3.0
		-	\dashv	\dashv			MInimum Water Quality
					-	\dashv	Parameters as set by State:
			\dashv	\rightarrow			pH 7.2
				+			
							·
	(N = No = Excur	sion)	To	tal N	's C	5	Print Name: Lunce Brooks
	, , ,						Signature: Jone Brooks
	Cand to Drinking Ma	stev D			til_t	10 -1	Date: ///29/22

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/