



# Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Date	Sample Location	pH	Alk	PO4	TEMP	
					Other	Y/N

<Has sample met the minimum(s)?

County: Clackamas Agency: CLACKAMA

## DISTRIBUTION

PWS ID 4194670

OREGON TRAIL SD - BORING MID SCH

Sample Period: 3/23  
Month/Year

Sample Frequency: Every 12 months

Distribution Samples required: 1

Number of excursions during this Sample Period = 0

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

### Reference

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Lance Brooks

Signature: Lance Brooks

Date: 3/31/23

(N = No = Excursion) Total N's 0

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>