

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County: Agency: CLACKAMA</th></has>	County: Agency: CLACKAMA
	1			l			met the	Clackamas
8/	VDH West Hall BF	75			150	0	minimum(s)?	DISTRIBUTION
8	1/24 Room 15	7.3			160	<u></u>		w)
							ll PW	S ID 4194670
8/	15/24 West Hall BF	7.5			15°0		OREGON TRAIL SD - BORING MID	
8/	15/24 ROOM 15	7.4			1700	_		SCH SD - BOKING WILD
							Commis Davis	1 + 1001
							Sample Period	Month/Year
					$-\parallel$		Sample Freque	ency: Every 12 months
							s •	amples required: 1
	•							
-		-	\dashv		\dashv	\dashv	Sample Period	ursions during this
			\dashv	\dashv		\dashv		tions when any WQP
			\dashv	-	\dashv	\dashv	was less than th	ne minimum.)
					- -	\exists	Note: Entry Poir	nt and Distribution
							Excursions are of	cumulative. Add Entry
							Point and Distrib total for sample	oution Excursions to get
							•	perioa.
							-Reference	
	•						BAT.	
							Parameter	Water Quality rs as set by State:
							pH 7.2	2
_ _								
_				4				
							Deint N	06/1/
(N = No = Excursion) Total N's						Print Name: Melseg Lincoln Lane		
	Date: 9/9/24							
	Send to Drinking Wat	er Pr	oara	m wii	thin 1	lO da		appalia a si al

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/