

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	P04	Other	Y/N	IIac campio	County: Agency: CLACKAMA Clackamas	
1/4	100 11) 11/11 DE	12	inn	F ==	i e	1/	met the minimum(s)?	DICTRIBUTION	
4/1	125 West Hall BP	7.4	120			1		DISTRIBUTION	
7//17	25 Karm 10	100	100			-	1	70.700 440 4670	
							PW	'S ID 4194670	
4/20	LOS Most 1/211 RF	7.4	120			Y	OREGON TRAIL SD - BORING MID		
1/20	25 Page 1/a	7.5			·	7		SCH	
700/	3 1009/1/19	7.5	IOU			/	Sample Perio	d: April 2025	
							Sample From	Month/rear	
							Sample Frequency: Every 12 months Distribution Samples required: 1		
							Distribution 3	parriples required.	
							Number of excursions during this Sample Period =		
								ations when any WQP	
					\dashv		was less than t		
						-	Note: Entry Poi	int and Distribution	
				•				cumulative. Add Entry bution Excursions to get	
_		_					total for sample		
				_			Reference		
							1.0.0.0.00		
\dashv							Minimum	Water Quality	
-+		-					Paramete	ers as set by State:	
	<u> </u>	\dashv	-+				pH 7.	.2	
				_		\dashv			
\top	·	_	$\neg \vdash$		\dashv		ľ		
		$\neg \vdash$		\neg		-			
	(N = No = Excursion) Total N's Print Name: Chelsea Lincoln Lane								
	Signature:								
	Sand to Drinking Water Bragram within 10 days of a sand of sand in the sand of sand of sand in the sand of sand of sand in the sand of sand of sand in the sand of								

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/