

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

						1 - 01 407/4144
ID#	Sample Location	рН	Alk	PO4 Othe	r Y/N	Has sample County: Agency: CLACKAMA Clackamas
		T . /	i -		1 ./	met the minimum(s)? DISTRIBUTION
1/05	West Hall BF	7.4	120	180	1 4	Distribution
2/25	Room 14	7.3	120	190	/	
					0 /	PWS ID 4194670
10/25	West Hall BF	7.5	120	18	1/	OREGON TRAIL SD - BORING MID
14/25	Room 16	7.4	120	190	11/	SCH
						Sample Period: September 2025 Month/Year
						Sample Frequency: Every 12 months
	***		(4)			Distribution Samples required: 1
	22					
					*	Number of excursions during this
						Sample Period =
			\			(Number of locations when any WQP was less than the minimum.)
2						
	2					Note: Entry Point and Distribution Excursions are cumulative. Add Entry
	νν					Point and Distribution Excursions to get
						total for sample period.
	10					Tiererenee
						Minimum Water Quality
			+			Parameters as set by State:
	Te: 27					pH 7.2
	19					
	ä					
7.	(1)	[9]				Print Name: Chelsea Lincoln Lar
	(N = No = Exc	ursior	n) T	otal N's	0	Signature:
(4)	(,		1	Date: <u>/0/2/35</u>
						days after and of campling period:

Send to Drinking Water Program within 10 days after end of sampling period:
OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: http://healthoregon.org/dwp/