



Water Quality Parameter Monitoring Form

Certification
Drinking Water Services

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Temp		Y/N
				Other		
1						
2						
3						
4						
5						
6						
7						
8						
9	7.3			19.3		Y
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26	7.2			19.5		Y
27						
28						
29						
30						
31						

<<Have minimums been met for this day?

County: Clackamas Agency: CLACKAMAS COUNTY

ENTRY POINT
EP-A

PWS ID 4194670

OREGON TRAIL SD - BORING MID SCH

Sample period: 6/23
Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality Parameter(s) as set by State:

pH 7.2

Print Name: Larue Brooks
Signature: Larue Brooks
Date & Phone#: 6/26/23

Send to DWP within 10 days after end of sampling period

(No = N = Excursion) Total N's 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>