

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2					
2 3 4					
4					
5					
6					
7	7.71				Y
8					•
9					
10					
11					
12					
13					
14	7.70	,			4
15					
16					
17					
18					
19		r			
20					
21	7.11				Y
22					•
23					
24					
25		v.			
26					
27					
28	7.77		8		y
29					
30					
31					
1 = oV	No = N = Excursion) <b>Total N's</b>				

< <have< td=""><td>County: Columbia Agency: COLUMBIA COUNTY</td></have<>	County: Columbia Agency: COLUMBIA COUNTY					
minimums	ENTRY POINT					
been met for this day?	EP-A					
PWS ID 4194717						
COLUMBIA RIVER PUD						
Sample period: May 2021						
-Month/Year						

Number of excursions during this month: \_\_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference					
Minimum Water Quality Parameter(s) as set by State:					
pH 7.2					

Print Name: _	I'M LAN	LMERS
Signature: _	Time	nues
		503-397-8155

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/