

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
2 3 4			111111111111111111111111111111111111111		
4					
5					
6	7.72				N
7					
8					
9					
10					
11					
12					
13					
14	7.73				N
15					
16					
17					
18					
19					
20					
21	7.75				N
22	`				
23	·				
24	·				
25					
26					
27	7.72				N
28					
29					
30					
31					
lo =	N = Ex	cursio	n) Tot a	al N's	D

< <have< th=""><th>County: Columbia Agency: COLUMBIA COUNTY</th></have<>	County: Columbia Agency: COLUMBIA COUNTY				
minimums	ENTRY POINT				
been met for this day?	EP-A				
	PWS ID 4194717				
COLUMBIA RIVER PUD					
Sample period: 7/23 Month/Year					

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2
Print Name: Grea Hollis

Date & Phone#: 8/1/2023 503/396/0529

Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Signature: (500000)

sampling period