

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2	7.76				Y
2 3 4					
4	7.67				Y
5					
6					
7					
8					
9	7.75				Y
10					
11					
12	7.75				Y
13					
14					
15					
16					
17	7.72				Y
18	7.64				Y
19					
20					
21					
22					<u> </u>
23	7.74				Y
24					
25	7.64				Y
26					
27					
28					
29					
30	7.72				Y
31					
10 = I	N = Ex	cursio	n) <b>Tot</b> a	al N's	C

< <have< th=""><th>County: Columbia Agency: COLUMBIA COUNTY</th></have<>	County: Columbia Agency: COLUMBIA COUNTY				
minimums	ENTRY POINT				
been met for this day?	EP-A				
•	PWS ID 4194717				
COLUMBIA RIVER PUD					
Sample pe	eriod: April zeoz el				
	Month/Year				

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Refe	erence
	Minimum Water Quality Parameter(s) as set by State:
	pH 7.2

Print Name: Greg Hollis
Signature: One of Hollis
Date & Phone#: 4/30/24 503.396.0529

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/