

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4	7.69				Y
2 3 4 5 6 7					
6	7.63				Y
8					
9					
10					
11	7.69				Y
12					
13	7.92				Y
14	,				
15	(3)				
16					
17					
18					
19					
20					
21	7.75				Y
22					
23			,		
24					
25	7,79				Y
26					
27	7.70				Y
28					
29					
30					
31					
lo = N	l = Exc	ursion	) Tota	l N's	0

< <have< td=""><td>County: Columbia Agency: COLUMBIA COUNTY</td><td></td></have<>	County: Columbia Agency: COLUMBIA COUNTY		
minimums	ENTRY POINT		
been met for this day?	EP-A		
	PWS ID 4194717		
	COLUMBIA RIVER PUD		
Sample pe	eriod: Feb 2025  Month/Year		

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2

Print Name: Greg Hollis
Signature: Greg Hollis
Date & Phone#: 3/4/2025 503-396-0529

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/