

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	AIK	Phos	Other	Y/N	< <have< th=""><th>County: Josephine Agency: JOSEPHINE COUNTY</th></have<>	County: Josephine Agency: JOSEPHINE COUNTY	
$\frac{1}{2}$						minimums		
2						been met for	ENTRY POINT	
3						this day?	EP-A	
<u>4</u> 5	7.5				Y	PWS ID 4194765 BECKLIN HOLDINGS INC		
6								
7							TO EDITOR INC	
8						Sample no	winds Tayyan Janan	
9						Sample period: January 2022		
	7/				-		Month/Year	
10 11	7.6				Y	Number of excursions during this month:		
12								
13						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are		
14						cumulative). A	In 'excursion' is any day in which the	
15						water quanty p	larameter(s) fall below the minimum	
16						set by the Stat	e.	
17	71				1/			
18	1,0					Referen	7ce	
19					_			
20						M	linimum Water Quality	
21						P	arameter(s) as set by State:	
22					_		pH 7.3	
23					_			
24 -	7.6				Y			
25					-			
26								
27								
28						Print Nar	me: William LABARGE	
29						Signatur	e: //////////	
30						Date & P	hone#: 1-31-22 541-476-8871	
	7,5					Send to D	OWP within 10 days after end of	
= N :	= Excu	ırsion)	Total	N's	2	sampling	period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/