

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>0</th></have<>	0	
1						minimums	County: Josephine Agency: JOSEPHINE COUNTY	
2						been met for	ENTRY POINT	
3						this day?	EP-A	
4							PWS ID 4194765	
5	7.5				Y	BECKLIN HOLDINGS INC		
6						_		
7						Somple ne	STATE Rev /2020	
8						Sample period: <u>SepTemBer</u> 2023 Month/Year		
9							Wohin/Year	
10	,					Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the		
	7.4				Y			
12					/			
13								
14						water quality parameter(s) fall below the minimum set by the State.		
15								
16								
17	1,/					Reference		
18 / 19	1.4				X			
20						Minimum Water Quality		
20						P	arameter(s) as set by State:	
22						pH 7.3		
23							·	
24 5	8							
	1.4							
26	W7				4			
27					/			
28						Print Name: CARMER BASSONI		
29						Signature: <u>[Baseven</u> Date & Phone#: <u>9/15/2013 54/-4/76-8</u> 8		
30								
31						Send to D	OWP within 10 days after end of	
o = N	= Excu	Irsion)	Total	N'e		sampling	period	
				L		ram PO Pox 142		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/