

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	PO4	other	Y/N	
							met the minimums? DISTRIBUTION
3		903				4	PWS ID: 41 9 4 8 6 5
							System Name: EASTGATE
7							Sample Period: FEB. ZOZ/ Month/Year
9		7.2%	7			7	Sample Frequency:
4						V	Distribution Samples required:
11		7.3				Y	Number of excursions during this Sample Period =
		7:	14			У	(Number of locations when any WQP was less than the minimum.)
16e		7.3		-	-	/	Note: Entry Point and Distribution
18		72.	7			Y	Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.
							For OHA use only
23		7.2	6	-		Y	Minimum Water Quality Parameters as set by
25		76	2			Y	pH 7.2
-		+		\vdash	<u> </u>		Alk (Alkalinity)
				-			PO4 (Orthophosphate)
							Other
							Print Name: GREGG OBERGA
	(N = No = Ex	cursion) T e	otal N	' s	0	Signature: 4-1-21

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/