

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Lane</th><th>Agency: LANE COUNTY</th></have<>	County: Lane	Agency: LANE COUNTY	
1						minimums	ENTRY	POINT	
2						been met for	EP		
3	1					this day?			
4						PWS ID 4195379			
5						EMERALD CHRISTIAN ACADEMY			
6							/		
7						Sample period: <u>July /Jul/</u> Month/Year			
8									
9						_			
10						Number of excursions during this month:			
11						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are			
12									
13	-) /					cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
14	7.4								
15						550 1.5 1.1.5			
17						Defere			
18						Refere	nce -		
19						I.	linimum Wate	er Quality	
20			<u> </u>					as set by State:	
21							[= =]		
22			<u> </u>				pH 7.2		
23									
24									
25									
26									
27						Print Na	me: B1//	l'entrella	
28	6,0				M	Signatu	17 11	BAUL	
29							Phone#: 7/3	8721	
30								0 days after end of	
31						sampling		,	
(No = I	No = N = Excursion) Total N's								

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/