

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County: Lane</th><th>Agency: I</th><th>ANE COUNT</th><th>ΓΥ</th></have<>		County: Lane	Agency: I	ANE COUNT	ΓΥ
1						minimum		ENTRY	POIN	IT	
2						been me			P-A		
3						this day?	,			_	
4								PWS ID 4	19537	9	
5	7.8					EMERALD CHRISTIAN ACADEMY					
6						9 9					
7						San	nple pe	riod: <u>//ece</u>	mber	1200	22
8									/lonth/Ye	, –	
9	7.2										
10						Numbe	er of ex	cursions du	ring this	s month	n: <u>    /   </u>
11								sions in 6 mor			
12		eysen min official states				Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the					
13								\n 'excursion' earameter(s) f			
14	-1						the Stat		ali belov	v tile illi	IIIIIIIIIIII
15	7.75					oor by	ino otat	0.			
16 17							_				
							Referer	nce -			
18 19							R.A	linimum Wat	or Oual	ity	
20								arameter(s)			:
21						19					
22								pH 7.2			
23	7.35										
24											
25											
26											
27							rint Na	me: Willia	n. Cei	1 fre//	á
28								re: Waller		the .	
29	7.8						•	Phone#: 2/		1236	541)63
30								DWP within 1			d of
31							ampling		o days	anci en	u Ui
o = N	1 = Exc	cursion	) Tota	l N's		3	~p9	, , , , , , , , , , , , , , , , , , , ,			
	OH	lA Dr	inking	Wate	r Pro	gram, PO	Box 14:	350, Portland	, OR 9	7293-03	350

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

My apologies for not sending during holidays