

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	
1 2 3 4 5 6 7						
3	,					
4						
5						
6						
	7.8					
8						
9						
10						
11						
12						
13						
14						
15	7,3					
16						
17						
18						
19						
20						
20 21 22 23 24						
22						
23						
	7.5					
25						
25 26 27 28 29 30			,			
27						
28						
29	,					
30						
31	7.2					
No = N = Excursion) Total N's						

<<Have
minimums
been met for
this day?</pre>

County: Lane Agency: LANE COUNTY

ENTRY POINT

EP-A

PWS ID 4195379

EMERALD CHRISTIAN ACADEMY

Sample period:

Month/Year

Number of excursions during this month: $\underline{\mathscr{O}}$

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Refe	erence ——			
	Minimum Paramete		Quality set by State:	
	pH 7.	2		
		4.4.1	7 1 1/	

Signature: William Centrella

Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/