

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other Y/N	< <have< th=""><th>County: Lane Agency: LANE COUNTY</th></have<>	County: Lane Agency: LANE COUNTY
1					minimums	ENTRY POINT
2					been met for	
3					this day?	EP-A
4				:	,	PWS ID 4195379
5					EME	RALD CHRISTIAN ACADEMY
6						1
7					Sample pe	eriod: AP(1/2025
8					Gumpio po	Month/Year
9	7.5					
10					Number of excursions during this month: $_$ $ ilde{ ilde{O}}$	
11					(Over 9 excur	sions in 6 months is a violation.
12						nd Distribution excursions are
13						An 'excursion' is any day in which the
14						parameter(s) fall below the minimum
15	2,4				set by the Sta	te.
16						
17					⊢Refere	nce
18						
19						Minimum Water Quality
20					F	Parameter(s) as set by State:
21						pH 7.2
22	7,6					
23			<u> </u>			
24						
25 26						
27	7					A his
28	7					ame: [vi//, an Centralla
29					Signatu	re: William But 10.
30	7,5				Date &	Phone#: <u>4/30/2824/346-12</u> 0
31	112				Send to	DWP within 10 days after end of
	l = E		\ T - 1		sampling	g period
110 = [v — ЕХ(Jursion)Tota	II N.S		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/