

## 2020 Cross Connection Annual Summary Report (ASR)

Water System Name and PWS ID# Rowena Dell Water System, 41-05372

System Size Small System, 1-299 connections

**Date Report was Received** 02/21/21 9:17 AM

ASR Contact Phil Rengler

Email Address ps.rengler@gmail.com

**Contact Phone Number** 541-478-3754

**Residential Connection 18** 

**High Hazard Connection**<sub>0</sub>

Other Connections 2

**Total Connections 20** 

**Enabling Authority** Yes

Did you revise your Enabling Authority? No

## This section for LARGE Systems Only

Cross Connection Specialist na

Specialist Cert #

WS Employee/Contracted

Phone #

**Email Address** 

## Written Backflow Protection Program

Written BFP program plan?

List of high hazards

Procedure

Notify Water Users

Type of Protection

Corrective Action

**Current Records** 

**Public Education** 



## 2020 Cross Connection Annual Summary Report (ASR)

Do you have any RPs? No
How many O
Tested
Passed
Failed
% of RPs tested
Comments

Do you have any DCs? Yes

How many 20

Tested 20

Passed 20

Failed 0

% of DCs tested 100%

Comments

Do you have any PVBs?No
How many<sup>0</sup>
Tested
Passed
Failed
% of PVBs Tested
Comments

I certify the information provided is true to the best of my knowledge. Providing false information may result in penalties to the individual and to the water system