

Water System Name and PWS ID# STAR SATELLITE IMPROV DIST, 41-00077 System Size Small System, 1-299 connections
Date Report was Received 04/04/23 8:53 AM ASR Contact Danni Parenteau Email Address bankssid@gmail.com Contact Phone Number +1 (503) 567-2904
Residential Connection 123 High Hazard Connection 0 Other Connections 0 Total Connections 123
Enabling Authority Yes Did you revise your Enabling Authority? No
This section for LARGE Systems Only
Cross Connection Specialist Specialist Cert # WS Employee/Contracted Phone # Email Address Written Backflow Protection Program Written BFP program plan? List of high hazards Procedure Notify Water Users Type of Protection Corrective Action Current Records Public Education

<p>Do you have any RPs? ^{No}</p> <p>How many</p> <p>Tested</p> <p>Passed</p> <p>Failed</p> <p>% of RPs tested</p> <p>Comments</p>
<p>Do you have any DCs? ^{Yes}</p> <p>How many ¹²³</p> <p>Tested ¹²³</p> <p>Passed ¹²⁰</p> <p>Failed ³</p> <p>% of DCs tested</p> <p>Comments The three double check backflow valves that failed were repaired and all passed upon retesting.</p>
<p>Do you have any PVBs? ^{No}</p> <p>How many</p> <p>Tested</p> <p>Passed</p> <p>Failed</p> <p>% of PVBs Tested</p> <p>Comments</p>

I certify the information provided is true ^{true} to the best of my knowledge. Providing false information may result in penalties to the individual and to the water system