

<b>Water System Name and PWS ID#</b>	UNION GAP WATER DISTRICT, 41-01371
<b>System Size</b>	Small System, 1-299 connections
<b>Date Report was Received</b>	02/28/21 2:48 PM
<b>ASR Contact</b>	KIM A. WATKINS
<b>Email Address</b>	KWATKINS1978@HOTMAIL.COM
<b>Contact Phone Number</b>	541-459-5776
<b>Residential Connection</b>	75
<b>High Hazard Connection</b>	0
<b>Other Connections</b>	2
<b>Total Connections</b>	77
<b>Enabling Authority</b>	Yes
<b>Did you revise your Enabling Authority?</b>	No
<b>This section for LARGE Systems Only</b>	
<b>Cross Connection Specialist</b>	na
Specialist Cert #	
WS Employee/Contracted	
Phone #	
Email Address	
<b>Written Backflow Protection Program</b>	
Written BFP program plan?	
List of high hazards	
Procedure	
Notify Water Users	
Type of Protection	
Corrective Action	
Current Records	
Public Education	

<p>Do you have any RPs? No</p> <p>How many 0</p> <p>Tested</p> <p>Passed</p> <p>Failed</p> <p>% of RPs tested</p> <p>Comments</p>
<p>Do you have any DCs? Yes</p> <p>How many 86</p> <p>Tested 77</p> <p>Passed 72</p> <p>Failed 5</p> <p>% of DCs tested 90%</p> <p>Comments OUT OF THE 86 DEVICES, 9 ARE ABANDONED RESIDENCES, LEAVING 77 DEVICES TO TEST. THE 5 WHICH FAILED WERE REPAIRED AND RE-TESTED AND PASSED TO EQUAL 77 TOTAL.</p>
<p>Do you have any PVBs? No</p> <p>How many 0</p> <p>Tested</p> <p>Passed</p> <p>Failed</p> <p>% of PVBs Tested</p> <p>Comments</p>

I certify the information provided is true to the best of my knowledge. Providing false information may result in penalties to the individual and to the water system