

October 27, 2016

Edward Borta
Mr. Rascal's, LLC
20275 Williams Highway
Williams, OR 97544

RE: Microscopic Particulate Analysis at the Mr. Rascal's public water system.

Dear Mr. Borta,

The Oregon Health Authority, Drinking Water Services (DWS) determined the groundwater well identified by well log #JOSE 17251 serving your water system must be evaluated for influence by surface water because of the presence of *E. coli* bacteria and its proximity to a drainage ditch. This evaluation is required by Oregon Administrative Rule (OAR) 333-061-0032(8). You must therefore collect the one remaining sample for microscopic particulate analysis as soon as possible but only after a period of heavy rainfall or snowmelt. Two additional samples may be necessary in the future depending on the results of this sample.

Please contact Shawn Stevenson at 541-726-2587, extension 32 if you have any questions about this letter and for a list of laboratories that can assist with the sampling and analysis.

If you do not complete the required sampling before the summer of 2017 you may be referred for further enforcement action, which could include the assessment of civil penalties according to OAR 333-061-0090.

Respectfully,



Brad K Daniels, Compliance Specialist
Oregon Health Authority, Drinking Water Services

cc: Justin Fimbres, Josephine County Environmental Health
Shawn Stevenson, Oregon Health Authority, Drinking Water Services