	Oregon Department						Parameter Monitoring Fo		
	of Human Services				Lead & Co	opper Rule Co	orrosion Control		
Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lane</th><th>Agency: REGION 2</th><th></th></have<>	County: Lane	Agency: REGION 2	
1	7.5	N/A	N/A	N/A	YES	minimums	$\neg$	ENTRY POINT	F
2	7.5	N/A	N/A	N/A	YES	been met for		Entry Point: EP-B	
3	7.5	N/A	N/A	N/A	YES	this day?		PWS ID 4100246B	
4	7.4	N/A	N/A	N/A	YES		System Name:	Creswell, City of	
5	7.4	N/A	N/A	N/A	YES		Sample period:	January-22	
6	7.5	N/A	N/A	N/A	YES			Month/year	
7	7.5	N/A	N/A	N/A	YES			·	
8	7.5	N/A	N/A	N/A	YES		Number of excursions during this month: <u>0</u>		
9	7.5	N/A	N/A	N/A	YES		(Over 9 excursions	in 6 months is a violation.	Ē
10	7.5	N/A	N/A	N/A	YES		Entry Point and Dis	tribution excursions are	
11	7.5	N/A	N/A	N/A	YES		,	cursion' is any day in which the	
12	7.5	N/A	N/A	N/A	YES			neter(s) fall below the minimun	
13	7.5	N/A	N/A	N/A	YES		set by the State.		
14	7.5	N/A	N/A	N/A	YES				
15	7.5	N/A	N/A	N/A	YES				
16	7.5	N/A	N/A	N/A	YES				
17	7.5	N/A	N/A	N/A	YES		Reference: Minimur	n pH set on 11/3/2003 By John Potts.	
18	7.4	N/A	N/A	N/A	YES				
19	7.5	N/A	N/A	N/A	YES		Minimum Water Q	-	
20	7.8	N/A	N/A	N/A	YES		Parameter(s) as se	et by State:	
21	7.8	N/A	N/A	N/A	YES				
22	7.7	N/A	N/A	N/A	YES		pH 7.1	(Aller limited)	
23 24	7.7 7.6	N/A N/A	N/A	N/A	YES YES		Alk N/A PO4 N/A	(Alkalinity)	
24 25	7.6	N/A N/A	N/A	N/A N/A	YES		Sili N/A	(Orthophosphate) (Silicate)	
25 26	7.6	N/A N/A	N/A N/A	N/A N/A	YES			(Sillale)	
20 27	7.7	N/A N/A	N/A N/A	N/A N/A	YES		Print Name:	Mike Howard	
		-			-		i mit Name.	mille Howard	
28	7.6	N/A	N/A	N/A	YES		Signature: Mil	ko Howard	
29	7.6	N/A	N/A	N/A	YES		Signature. Will		
30	7.6	N/A	N/A	N/A	YES		-	541-736-6015	
31	7.6	N/A	N/A	N/A	YES			2/3/2022	
=Excursio	on) Total N's					Send to DWP	within 10 days after end	d of sampling period	