	DHS Oregon Department					Water Quality Parameter Monitoring Form		
	of Human Services				Lead 8		Corrosion Control	
Day	pН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lane Agency: REGION 2</th></have<>	County: Lane Agency: REGION 2	
1	7.5	40	N/A	N/A	YES	minimums	ENTRY POINT	
2	7.4	44	N/A	N/A	YES	been met for	Entry Point: EP-B	
3	7.4	42	N/A	N/A	YES	this day?	PWS ID 4100246B	
4	7.5	44	N/A	N/A	YES		System Name: Creswell, City of	
5	7.5	44	N/A	N/A	YES		Sample period: July-24	
6	7.5	42	N/A	N/A	YES		Month/year	
7	7.5	42	N/A	N/A	YES			
8	7.5	40	N/A	N/A	YES		Number of excursions during this month:0	
9	7.6	38	N/A	N/A	YES		(Over 9 excursions in 6 months is a violation.	
10	7.5	40	N/A	N/A	YES		Entry Point and Distribution excursions are	
11	7.5	40	N/A	N/A	YES		cumulative). An 'excursion' is any day in which the	
12	7.5	40	N/A	N/A	YES		water quality parameter(s) fall below the minimun	
13	7.5	40	N/A	N/A	YES		set by the State.	
14	7.4	40	N/A	N/A	YES			
15	7.4	40	N/A	N/A	YES			
16	7.5	38	N/A	N/A	YES			
17	7.4	38	N/A	N/A	YES		Reference: Minimun pH set on 11/3/2003 By John Potts.	
18	7.4	38	N/A	N/A	YES			
19	7.4	40	N/A	N/A	YES		Minimum Water Quality	
20	7.4	40	N/A	N/A	YES		Parameter(s) as set by State:	
21	7.4	40	N/A	N/A	YES	_		
22	7.4	40	N/A	N/A	YES	_	pH 7.1	
23	7.5	38	N/A	N/A	YES		Alk 33 (Alkalinity)	
24	7.4	38	N/A	N/A	YES	_	PO4 N/A (Orthophosphate)	
25	7.4	40	N/A	N/A	YES	-	Sili N/A (Silicate)	
26	7.4	40	N/A	N/A	YES	-	Print Name: Mike Howard	
27	7.5	40	N/A	N/A	YES	_		
28	7.4	40	N/A	N/A	YES	_	Circuit (1997) Millio Hannan I	
29	7.4	40	N/A	N/A	YES		Signature: Mike Howard	
30	7.5	42	N/A	N/A	YES		541-736-6015	
31	7.5	42	N/A	N/A	YES		8/1/2024	
I=Excurs	sion)		Total N's			Send to DWP w	vithin 10 days after end of sampling period	
					DHS, Drin	king Water Program	n, PO Box 14350, Portland, OR 97293-0350	