## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N
1	8	48			У
3	7.9	44			У
3	7.8	44			У
4	7.7	44			У
5 6	7.6	48			У
	7.6	48			У
7	7.8	48			У
8	8	48			У
9	7.8	52			У
10	7.9	52			У
11	7.7	52			У
12	7.8	48			У
13	8	52			У
14	8.2	52			У
15	8	48			У
16	7.8	48			У
17	7.9	44			У
18	8	48			у
19	7.8	48			У
20	7.8	48			У
21	7.8	48			У
22	7.8	48			У
23	7.9	48			У
24	8	48			У
25	7.7	44			у
26	7.8	44			У
27	7.7	48			У
28	8	52			у
29	8.1	44			У
30	7.9	44			У
31					
(No=N	(No= N=Excursion) Total N's				0

< <have minimums been</have 	ENTRY POINT				
met for this day?	EP-A				
	PWS ID 4100323				
GLENDALE, CITY OF					
Sample P	Period: (Month/Year) April	2025			

Number of excursions during this month:

(

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution Excursions are cumulative.) An 'Excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality

Parameter(s) as set by State:

pH: 7.3

Print Name:

Sean Negberbon

Signature:

Date

period

Send to DWP within 10 days after end of sampling

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp