vvater quality rarameter monitoring roim



## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: C</th></have<>	County: Clackamas Agency: C	
أعان	7.86		13		14	minimums been met for	ENTRY POINT	
20	788		1.3		9	this day?	A.	
							PWS ID 4100547	
							MULINO WATER DISTRICT	
						Sample period: 112024		
							Month/Year	
					-			
						Number of excursions during this month: Over 9 excursions in 6 months is a violation. Entry		
					-			
						Point and Distribution excursions are cumulative).  An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
					1			
-			4		+			
			1			-Ref	erence	
							Minimum Water Quality	
			-	1	-		Parameter(s) as set by State:	
-			-				pH 7.3	
					-			
		-		-	-			
	1			1	+			
						Print Na	me: NARVIN IROGPON	
						Signatur	e: Man Turky	
No =	N = Ex	cursio	n) <b>Tot</b> a	al N's	0	Date:	11/21/2024	
Send to DWP within 10 days after end of sampling period								

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp