

Water Quality Parameter Monitoring Form  
Oregon Department of Human Services  
**Lead & Copper Rule Corrosion Control**

Day	PH	Y/N
1	8.0	Y
2	8.0	Y
3	8.0	Y
4	7.9	Y
5	8.0	Y
6	7.9	Y
7	7.9	Y
8	7.9	Y
9	7.9	Y
10	7.9	Y
11	7.9	Y
12	7.9	Y
13	7.9	Y
14	7.9	Y
15	7.9	Y
16	7.8	Y
17	7.8	Y
18	7.9	Y
19	7.9	Y
20	7.9	Y
21	8.0	Y
22	7.9	Y
23	8.0	Y
24	8.0	Y
25	8.1	Y
26	8.0	Y
27	8.0	Y
28	8.0	Y
29	8.0	Y
30	8.0	Y
31	8.0	Y
<b>Total N's</b>	<b>0</b>	

<<Have minimums been met for this day?

County: Lincoln Agency: REGION 2  
**ENTRY POINT**  
EP- A (WTP)  
**PWS ID 4100566**  
City of Newport  
Sample period: Jan-21

**Number of excursions during this month:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).  
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality  
Parameter(s) as set by State:**

pH 7.0

Print Name: Steve Stewart

Signature: 

Date: 2/2/2021

Sent to DWP within 10 days after end of sampling period.

(No = N = Excursion)