

Water Quality Parameter Monitoring Form  
Oregon Department of Human Services  
**Lead & Copper Rule Corrosion Control**

Day	PH	Y/N	<<Have minimums been met for this day?
1	8.0	Y	
2	8.1	Y	
3	8.0	Y	
4	8.0	Y	
5	8.0	Y	
6	8.0	Y	
7	7.9	Y	
8	7.9	Y	
9	7.9	Y	
10	7.9	Y	
11	7.9	Y	
12	7.9	Y	
13	7.8	Y	
14	7.8	Y	
15	7.9	Y	
16	7.9	Y	
17	7.9	Y	
18	7.9	Y	
19	7.9	Y	
20	7.8	Y	
21	7.8	Y	
22	7.9	Y	
23	7.9	Y	
24	7.9	Y	
25	7.9	Y	
26	8.0	Y	
27	8.0	Y	
28	8.0	Y	
29	8.0	Y	
30	8.0	Y	
31	8.0	Y	
<b>Total N's</b>		<b>0</b>	

(No = N = Excursion)

<<Have minimums been met for this day?

County: Lincoln

Agency: REGION 2

**ENTRY POINT**  
EP- A (WTP)  
**PWS ID 4100566**  
City of Newport

Sample period: Jan-22

**Number of excursions during this month:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).  
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

<b>Minimum Water Quality Parameter(s) as set by State:</b>	
pH	<b>7.0</b>

Print Name: Steve Stewart

Signature: 

Date: 2/1/2022

Sent to DWP within 10 days after end of sampling period.