

Water Quality Parameter Monitoring Form  
Oregon Department of Human Services  
**Lead & Copper Rule Corrosion Control**

Day	PH	Y/N
1	8.1	Y
2	8.0	Y
3	8.0	Y
4	8.0	Y
5	8.0	Y
6	8.0	Y
7	8.0	Y
8	8.0	Y
9	8.0	Y
10	8.1	Y
11	8.1	Y
12	8.1	Y
13	8.1	Y
14	8.1	Y
15	8.2	Y
16	8.2	Y
17	8.2	Y
18	8.1	Y
19	8.1	Y
20	8.1	Y
21	8.1	Y
22	8.1	Y
23	8.0	Y
24	8.0	Y
25	8.0	Y
26	7.9	Y
27	7.9	Y
28	7.9	Y
29	7.9	Y
30	7.9	Y
31	7.9	Y
<b>Total N's</b>		<b>0</b>

(No = N = Excursion)

<<Have minimums been  
met for this day?

County: Lincoln

Agency: REGION 2

**ENTRY POINT**

EP- A (WTP)

**PWS ID 4100566**

City of Newport

Sample period: Mar-22

**Number of excursions during this month:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).  
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference


**Minimum Water Quality  
Parameter(s) as set by State:**

pH

**7.0**

Print Name: Steve Stewart

Signature:



Date: 4/3/2022

Sent to DWP within 10 days after end of sampling period.