

**Water Quality Parameter Monitoring Form
Oregon Department of Human Services
Lead & Copper Rule Corrosion Control**

Day	PH	Y/N
1	7.7	Y
2	7.7	Y
3	7.5	Y
4	7.6	Y
5	7.5	Y
6	7.4	Y
7	7.3	Y
8	7.6	Y
9	7.6	Y
10	7.7	Y
11	7.9	Y
12	8.0	Y
13	8.0	Y
14	8.0	Y
15	8.0	Y
16	8.0	Y
17	8.0	Y
18	7.9	Y
19	7.8	Y
20	7.8	Y
21	7.7	Y
22	7.7	Y
23	7.9	Y
24	7.9	Y
25	7.9	Y
26	8.1	Y
27	8.1	Y
28	8.0	Y
29	8.0	Y
30	7.9	Y
31	7.8	Y
Total N's	0	

<<Have minimums been met for this day?

County: Lincoln Agency: REGION 2
ENTRY POINT
 EP- A (WTP)
PWS ID 4100566
 City of Newport
 Sample period: Jul-24

Number of excursions during this month: 0


(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).
 An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.0

Print Name: Steve Stewart

Signature: 

Date: 8/5/2024

Sent to DWP within 10 days after end of sampling period.