

Water Quality Parameter Monitoring Form
Oregon Department of Human Services
Lead & Copper Rule Corrosion Control

Day	PH	Y/N
1	7.8	Y
2	7.8	Y
3	7.8	Y
4	7.8	Y
5	7.8	Y
6	7.8	Y
7	7.7	Y
8	7.7	Y
9	7.8	Y
10	7.8	Y
11	7.8	Y
12	7.8	Y
13	7.9	Y
14	7.9	Y
15	7.9	Y
16	7.9	Y
17	7.9	Y
18	8.0	Y
19	8.0	Y
20	7.8	Y
21	7.9	Y
22	7.9	Y
23	7.9	Y
24	7.9	Y
25	7.9	Y
26	7.9	Y
27	7.9	Y
28	8.0	Y
29	8.0	Y
30	8.0	Y
31	8.1	Y
Total N's		0

(No = N = Excursion)

<<Have minimums been
met for this day?

County: Lincoln

Agency: REGION 2

ENTRY POINT

EP- A (WTP)

PWS ID 4100566

City of Newport

Sample period: Dec-25

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH

7.0

Print Name: Steve Stewart

Signature: 

Date: 1/5/2026

Sent to DWP within 10 days after end of sampling period.