

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.85	38.3			Y
2					
4					
5					
6					
7					
8	7.60	44.0			7
9					
10					
11					
12					
13					
14					
15	7.71	31.3			Y
16					
17					
18					
19					
20					
21					
22	7.74	32.5			4
23					
24					
25					
26					
27					
28					
29	7.81	34.4			4
30					
31					
1 = oV	1 = Exc	ursion) Tota	I N's	d

< <have< th=""><th>County: Clackamas Agency: REGION 1</th></have<>	County: Clackamas Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-B
-	PWS ID 4100580
NORT	H CLACKAMAS COUNTY WC
Sample pe	riod: 7 / 2024

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	num Water Quality neter(s) as set by State
pH Alk	7.5 25.0 (Alkalinity)
rint Name:	Joseph Rogers

Print Name: Joseph Rogers
Signature: B-2-Z4

Send to DWP within 10 days after end of sampling period