



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

| Day | pH | Alk | Phos | Other | Y/N |
|-----|-----|-----|------|-------|-----|
| 1 | 7.7 | | | | Y |
| 2 | 7.6 | | | | Y |
| 3 | 7.6 | | | | Y |
| 4 | 7.6 | | | | Y |
| 5 | 7.5 | | | | Y |
| 6 | 7.6 | | | | Y |
| 7 | 7.5 | | | | Y |
| 8 | 7.5 | | | | Y |
| 9 | 7.7 | | | | Y |
| 10 | 7.5 | | | | Y |
| 11 | 7.5 | | | | Y |
| 12 | 7.4 | | | | Y |
| 13 | 7.7 | | | | Y |
| 14 | 7.5 | | | | Y |
| 15 | 7.5 | | | | Y |
| 16 | 7.4 | | | | Y |
| 17 | 7.4 | | | | Y |
| 18 | 7.6 | | | | Y |
| 19 | 7.7 | | | | Y |
| 20 | 7.4 | | | | Y |
| 21 | 7.4 | | | | Y |
| 22 | 7.6 | | | | Y |
| 23 | 7.6 | | | | Y |
| 24 | 7.4 | | | | Y |
| 25 | 7.3 | | | | Y |
| 26 | 7.4 | | | | Y |
| 27 | 7.7 | | | | Y |
| 28 | 7.4 | | | | Y |
| 29 | 7.7 | | | | Y |
| 30 | 7.7 | | | | Y |
| 31 | 7.5 | | | | Y |

<< Have minimums been met for this day?

County: Tillamook Agency: REGION 1

ENTRY POINT

A

PWS ID 4100708

Rockaway Beach Water Dist.


Sample Period: Mar-24
Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative), An 'excursion' is anyday in which water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:

pH 7.2

Print Name: Luke Shepard
Signature: 
Date: 4/2/24

(No = N = Excursions) **Total N's** 0

Send to DWP within 10 days after end of sampling period
DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone: (503) 732-4381 Website: www.ohd.hr.state.or.us/dwp