

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.5	A -			Y
2	7.5	B. Marian			\/
3	7.5				\ \ \
4	7.5				1
5	7.4				Y
6	7.6				Y
7	7.6				Y
8	7.6				Y
9	7.3				14
10 11	7.2				4
11	7.5				Y
12	7.6				V
13	7.5	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			Y
14	7.5		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		y
15	7.6				y
16	7,5				9
17	7.3				Y
18	7.7				4
19	7.7				4
20	7.5				1
21	7.2				Y
22	7.3	A TOP IN THE REAL PROPERTY.			V
23	7.4				4
24	7.6				1
25	7.6	San Arch	1	1	14
26	7.1				4
27	7.6	v			1
28	7.7				4
29	OFF				
30	80				4
31	-			-	

< <have< th=""><th>County: Columbia Agency: REGION 1</th></have<>	County: Columbia Agency: REGION 1		
minimums	ENTRY POINT		
been met for this day?	EP-A		
	PWS ID 4100792		
	SCAPPOOSE, CITY OF		
Sample p	eriod: SEPT ZOZI		
	Month/Year		

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Number of excursions during this month: _

Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk (Alkalinity)
Print Name: Darry Sykes Signature: Dorry Sykes
Date & Phone#: 10 8 202 503-369-0297
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Reference