

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	8.2				\)
3	8.0				<i>Y Y</i>
	8.0				7
4	7.8				V
5	7.8				7
6	7.9				4
7	7.9				/
8	7.8				Y
9	7.7				7
10	7.8				4
11	7.7				У
12	7.7				/
13					4
14	7.6				y
15	7.6 7.4 7.9 7.5 7.4				+
16	7.9				Y
17	7.5				*/
18 19	7.4				7
20	7-12				7
21	7.2				Y
22	7.5				7
23	7.5 7.5				7
24	7.6				Y
25	7.5				7
26	7.5				7
27	7.3			r la	4
28	7.7				7
29	7.7				4
30	7.3				4
31	7.5				y
No = N	I = Exc	ursion) Total	N's	0

< <have minimums been met for</have 	County: Columbia Agency: REGION 1 ENTRY POINT			
this day?	EP-A			
	PWS ID 4100792			
	SCAPPOOSE, CITY OF			
Sample pe	riod: July 2022 Month/Year			
*	Month/Year			

Number of excursions during this month:

Reference

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk (Alkalinity)
Print Name: Darry Sykes
Signature: Darry Lykes
Date & Phone#: 8/4/2022 503-369-0297
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/