## $\mathsf{OHA}$

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

<< Have

this day?

minimums

been met for

Day	pН	Alk	Phos	Other	Y/N
1					
2					
3					
4	8.1		0.6		Υ
5	8.1		0.7		Υ
6				The state of the s	
7					
8					
9					
10					
11					
12					
13					
14	8.1		0.6		Υ
15	8.1		0.6		Υ
16	8.1		0.5		Υ
17					
18	8.1		0.7		Υ
19	8.1		0.6		Υ
20	8.1		0.6		Υ
21	8.1		0.6		Υ
22					
23					
24					
25	8.0		0.6		Υ
26	8.1		0.6		Υ
27	8.1		0.6		Υ
28	8.1		0.5		Υ
29	8.1		0.6		Υ
30	8.1		0.7		Υ
31					
(No = N =	No = N = Excursion) Total N's			0	

Well inspected daily. Samples collected when well is operating at time of inspection NR = Well not running during inspection

County: Wasco

Agency: REGION 1

**Lone Pine Well ENTRY POINT** 

EP-B

PWS ID 41-00869 THE DALLES, CITY OF

Sample period: July 2021

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference				
Minimum Water Quality Parameter(s) as set by the State:				
pH TBD				
PO4 0.4 (Orthophosphate)				
Assessment Monitoring				

Print Name: Larry McCollum

Date & Phone: 4 Aug 2021; 541-298-2248 x 5000

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp