## OHA

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other		<< Have	County: Wasco Agency:	DECION 4
1					,	minimums		REGION 1
2						been met for Lone Pine Well		
3						this day?	ENTRY POIN	T
4								
5						1	EP-B	
6						1	PWS ID 41-008	260
7							THE DALLES, CITY	
8								/ OF
9							Sample period: September 2021	
10	8.1		0.4		Υ	Nu	mber of excursions during this mon	th: 0
11								· · · · · ·
12						Over 9 exc	ursions in 6 months is a violation. For	ation . Deline
13						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any		
14						day in whic	h the water quality parameter(s) for	all helow the
15	8.1		0.5		Υ	minimum set by the State.		
16								
17						Reference		
18								
19							Minimum Water Quality	
20	8.1		0.5	9	Υ		Parameter(s) as set by the Sta	ate:
21								
22							pH 7.8	
24								
25							O4 0.4 (Orthophosphate)	
26								
27						<u> </u>		
28						Duint Name		
29						Print Name:	Larry McCollum	
30	8.1		0.5		Υ	Signature:	JANE LL	_
No = N = Excursion) Total N's 0 Date & Phone: 04 Oct 2021; 541-298-2248 x 5000								
Well inspected daily. Samples collected when								

Well inspected daily. Samples collected when well is operating at time of inspection NR = Well not running during inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp