Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1				OFF		minimums		
2				OFF		been met for	Lone Pine Well	
3				OFF		this day?	ENTF	RY POINT
4				OFF			_	
5				OFF		1	E	P-B
6				OFF		PWS ID 41-00869		
7				OFF		THE DALLES, CITY OF		
8				OFF				
9				OFF		Sample period: March 2022		
10				OFF		Number of excursions during this month: 0		
11				OFF				
12				OFF		(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
13				OFF				
14				OFF				
15				OFF				
16				OFF				
17				OFF		Reference		
18				OFF				
19				OFF			Minimum Water Qua	ality
20				OFF			Parameter(s) as set by the State:	
21				OFF				
22				OFF		pH 7.8		
23				OFF				
24				OFF		PO4 0.4 (Orthophosphate)		
25				OFF				
26				OFF				
27				OFF				
28				OFF		Print Name: Larry McCollum Signature:		
29				OFF				
30	_			OFF				
	011						e: 08 Apr 2022; 541-298-	2248 x 5000
(NO = N =	No = N = Excursion) Total N's 0							

Send to DWP within 10 days after the end of the sampling period

Well inspected daily. Samples collected when well is operating at time of inspection NR = Well not running during inspection

OFF = Well off for the season

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp