OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

<< Have

this day?

minimums

been met for

	·			u u u	JOPI
Day	рН	Alk	Phos	Other	Y/N
1				OFF	
2				OFF	
3				OFF	
4				OFF	
5				OFF	
6				OFF	
7				OFF	
8				OFF	
9				OFF	
10				OFF	
11				OFF	
12				OFF	
13				OFF	
14				OFF	
15				OFF	
16				OFF	
17				OFF	
18				OFF	
19				OFF	
20				OFF	
21				OFF	
22				OFF	
23				OFF	
24				OFF	
25				OFF	
26				OFF	
27				OFF	
28				OFF	
29				OFF	
30				OFF	
31				OFF	
(No = N = Excursion)			To	tal N's	0

Well inspected daily. Samples collected when well is operating at time of inspection

NR = Well not running during inspection

OFF = Well off for the season

County: Wasco

Agency: REGION 1

Lone Pine Well ENTRY POINT

EP-B
PWS ID 41-00869
THE DALLES, CITY OF

Sample period: May 2022

Number of excursions during this month:

0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Ref	erence
-----	--------

Minimum Water Quality
Parameter(s) as set by the State:

pH 7.8

PO4 0.4 (Orthophosphate)

Print Name: Larry McCollum

Signature: /

Date & Phone: 06 Jun 2022; 541-298-2248 x 5000

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp