OHA

Well inspected daily. Samples collected when

well is operating at time of inspection

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other	Y/N	<< Have	County: Wasco Agen	cy: REGION 1
1						minimums	Lone Pine Well	
2	W					been met for		
3	е				12 (a. 16)	this day?	ENIRTPO	IIN I
4	- 1						EP-B	
5	100						<u> </u>	
6							PWS ID 41-0	00869
7	o f						THE DALLES, O	CITY OF
8	f						Sample period: January 2025	
9		10000000						
10	f					N	umber of excursions during this r	nonth:0
11	o							
12	r			Sections.		(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
13								
14	e		70.00					
15	1							
16	e c		1000000000	0.5.60				
17	t					Referenc	e	
18	r						Minimum Mator Ovelity	
19	i					Minimum Water Quality		
20	С						Parameter(s) as set by the	e State:
22	а							
23	- 1						pH 7.8	
24							PO4 0.4 (Orthophospho	rtal
25	r e						Cortinophiosphic	ne,
26	р							
27	a							
28	i					Print Name	v Tuler Mitthell 1	
29	r					Print Name: Tyler Mitchell		
30	S			isi ee ee	0.00	Signature:_	HUM	
31						Date & Pho	one: 4-Feb-25 541	-298-2248 x 5010
No = N	= Excur	sion)	T.	otal N's	0	Date Grit	c. 7 (CD-25 341	230-2240 X 3010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp