## OHA

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рΗ	Alk	Phos	Other	Y/N	<< Have	County: Wasco Agency: REGION 1	
1						minimums	Lone Pine Well	
2						been met for		
3	W					this day?	ENTRY POINT	
4	e						EP-B	
5								
6			ļ			_	PWS ID 41-00869	
7							THE DALLES, CITY OF	
8	o				ļ		Sample period: March 2025	
9	f				<u> </u>		value period. Walti 2025	
10	f					N	umber of excursions during this month: 0	
11						-		
12	f				ļ	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any		
13	0							
14	r		ļ			day in which the water quality parameter(s) fall below the		
15	e					minimum set by the State.		
16	1					ļ <u> </u>	~~~~	
17	е				<u> </u>	Referenc	ce	
18	С				-	4	BACULTURE NAME AND CONTROL	
19	t						Minimum Water Quality	
20	r					_	Parameter(s) as set by the State:	
21	i				-			
22	C a						pH 7.8	
23					-	PO4 0.4 (Orthophosphate)		
-				ļ	<del> </del>	-	PO4 0.4 (Orthophosphate)	
25	r			-	-	1		
26	e		<del>                                     </del>	ļ	<del>                                     </del>		Transaction of the second of t	
27	р			-	1	Duine Norma	n. Tulov Mitchell 4	
28	a					Print Name	e: Tyler Mitchell	
29	i			***************************************		Signature: W/W//		
30	r s					Date & Pho	one: 2-Apr-25 541-298-2248 x 5010	
1		sion)	Т	otal N's	0	- Date of File	511-230-2248 X 3010	
(No = N = Excursion) Total N's 0								

Well inspected daily. Samples collected when well is operating at time of inspection NR = Not running at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp