

OHA

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

County: Wasco Agency: REGION 1

**Lone Pine Well
ENTRY POINT**

EP-B

**PWS ID 41-00869
THE DALLES, CITY OF**

Sample period: February 2026

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by the State:**

pH

PO4 (Orthophosphate)

Day	pH	Alk	Phos	Other	Y/N	<< Have minimums been met for this day?
1						
2						
3						
4						
5						
6	8.0		0.4		Y	
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19	8.0		0.6		Y	
20						
21						
22						
23	8.1		0.5		Y	
24						
25						
26						
27						
28						

(No = N = Excursion) Total N's

Well inspected daily. Samples collected when well is operating at time of inspection

Print Name: Tyler Mitchell

Signature: 

Date & Phone: 09-Mar-26 541-298-2248 x 5010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp>