OHA

well is operating at time of inspection

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1	100			200		minimums	Iordan Well	
2						been met for	ENIT	RY POINT
3						this day?	ENTI	AT POINT
4							1	EP-C
5	w	3.00						
6	e						PWSII	D 41-00869
7	- 1						THE DA	LLES, CITY OF
8	1						Sample period: Decer	nber 2024
9		-153		32751010				
10	0					Number of excursions during this month: 0		
11	f							
12						(Over 9 excursions in 6 months is a violation. Entry Point and		
13	f		SACRESS NO.			Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
14	0							
15	r							
16								
17	t	-				Referenc	ce	
18	h						Minimum Water O	uality
19	e					Minimum Water Quality Parameter(s) as set by the State:		
20							Parameter(s) as set	by the State:
22	s e						pH 7.8	
23	a						рп 7.6	
24	s						PO4 0.4 (Ortho	phosphate)
24 	0					and services of the services o	0.4 0.4	μποεμπατεχ
	n							
26								
27 28						Drine Name	a. Tular Mitchall	
						Print Name: Tyler Mitchell Signature: Tylumum		
30								
	= Excui		 	otal N's	0	Date & Ph	// one: 9-Jan-25	541-298-2248 x 5010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp