## OHA

well is operating at time of inspection

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos		Y/N	<< Have	County: Wasco	Agency: REGION 1		
1	Not Running					minimums been met for this day?  Jordan Well ENTRY POINT				
2	Not Running									
3	Not Running									
4	Not Running						•	ED C		
5	8.2 0.8			У	EP-C					
6	Not Running					PWS ID 41-00869				
7	Not Running					THE DALLES, CITY OF				
8	Not Running					Sample period: March 2025  Number of excursions during this month: 0				
9	Not Running									
10	Not Running									
11	Not Running					]				
12	Not Running					(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.  Reference				
13	Not Running									
14	Not Running									
15	Not Running									
16	Not Running									
17	Not Running									
18	Not Running					]				
19	Not Running					Minimum Water Quality Parameter(s) as set by the State:				
20	Not Running				<u>.</u>					
21	Not Running					_				
22	Not Running					]	pH 7.8			
23	Not Running									
24	Not Running					PO4 0.4 (Orthophosphate)				
25	Not Running					]				
26		ot Runni			ļ					
27	N	Not Running				_	Tulon Mitab A	A		
28	Not Running					Print Name: Tyler Mitchell Signature:				
29	Not Running									
30	N	ot Runni	ng							
31		ot Runni				Date & Pho	one: 4-Apr-25	541-298-2248 x 5010		
(No = N = Excursion) Total N's 0  Well inspected daily. Samples collected when Send to DWP within 10 days after the										

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp

end of the sampling period