

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y	/N	
1	7.90						
1 2 3 4	7.90						
3	7.90				Н	_	
4	7.90						
5	7.90						
6	7.90						
7	7.90						
8	7.90				Н	_	
9	7.90				H	_	
10	7.90				Н	-	
11	7.90				H		
12	7.80				$\dagger \dagger$		
13	7.80				H		
14	7.80				H	_	
15	7.90				H	-	
16	7.90				$\dagger \dagger$		
17	7.90				Ħ		
18	7.80				Ħ		
19	7.90				П		
20	7.90						
21	7.90						
22	7.80						
23	7.80				3		
24	7.80			411			
25	7.80						
26	7.80			1			
27	7.80						
28	7.80				3		
29	7-80		e de la companya de l	1 AL			
30	7.80		100	a de			
31	7.80		100	9,00	1	Ŋ	
No = N = Excursion) Total N's							

<<Have minimums been met for this day?

County: Washington Agency: REGION 1

ENTRY POINT

EP-A

PWS ID 4100898 TIMBER WATER ASSOCIATION

Sample period: December - 2023

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Refe	rence ——			
	Minimum \ Parameter	Nater Qu (s) as se	uality et by State:	
	pH 7.2	2		
			*	
273.00				
Print I	Name:	Tabata	fleidt	
Signa	ture:	Lieu	df.	
Date 8	Phone#:	01-07-	24	
Send t	o DWP with	in 10 day	s after end	of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/