

(No = N = Excursion) Total N's

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk Ph	os Othe	r Y/N	< <have entry="" point<="" th=""></have>
1	714			Y	minimums been met for
2	7.4			4	this day? PWS ID: 41 00966
3	7.4			Y	System Name: City of Jachals
4	7.7			Y	TOND TO
5	74			У	1 0 0011
6	7.4			ý	Sample Period: Sept. 2029  Month/Year
7	7,4			Y	
8	7.4			79	Number of excursions* during this month:
9	73			λ	(Count the number of days when any WQP was
10	7:3			Y	less than the minimum required)
11	フル			Y	
12	7.H			Y	Total excursions during the previous 5 months:_
13	7.7			Y	(Over 9 excursions in 6 months is a violation. Entry
14	7.2			Y	Point and Distribution excursions are cumulative)
15	7.2			Y	For OHA use only
16	73			λ	
17	7.2			У	Minimum Water Quality
18	7.7			Y	Parameters as set by
19	7,2			Y	pH 7.0
20	7,3			Y	Alk / (Alkalinity)
21	7,3			Y	PO4 (Orthophosphate)
22	7,4			Y	Other (Orthophiate)
23	74			1	Ouiei
24	7.4			Ý	
25	7.4			Y	
26	7.4			Y	
27	7.4			Y	Print Name: Kirk Wellung
28	7.4			Y	Signature: K. Mallunk
29	7.4			1 Y	Date: 10/14/24
30	7.4			4	Send to DWP within 10 days after end of
31					sampling period
<b>()</b> I	A 1 Pm		- 4 1 50	CV	3 Company Paris

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/