

## Lead & Copper Rule Corrosion Control

AUTHORITY

Day	Ph	Alk	Phos	Sili	Y/N	<< Have Minimums Been Met for this day
1						
2	7.5				Y	
3	7.6				Y	
4						
5	7.5				Y	
6	7.4				Y	
7						
8						
9	7.6				Y	
10						
11	7.3				Y	
12						
13	7.4				Y	
14						
15						
16						
17	7.4				Y	
18	7.7				Y	
19						
20	7.8				Y	
21						
22						
23	7.6				Y	
24						
25	7.5				Y	
26	7.5				Y	
27						
28						
29						
30	7.7				Y	
31						
No = N = Excursion					<b>Total N's</b>	0

County: Josephine Agency: 5  
**Entry Point**  
**A**  
**PWS ID 4100971**  
**Cave Junction, City of**

Sample Period:  
 Month/Year Jan. 2023

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality  
 Parameter(s) as set by State:**

pH 7.3

Print Name: Steven Bethke  
 Signature: Steven Bethke  
 Date: 2-6-23

Send to DWP within 10 days after end of sampling period  
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp