

Lead & Copper Rule Corrosion Control

AUTHORITY

Day	Ph	Alk	Phos	Sili	Y/N	<< Have Minimums Been Met for this day
1						
2	7.4				Y	
3						
4						
5	7.5				Y	
6						
7						
8	7.5				Y	
9						
10						
11						
12	7.6				Y	
13						
14						
15						
16	7.6				Y	
17						
18						
19	7.4				Y	
20						
21						
22						
23						
24	7.4				Y	
25						
26	7.4				Y	
27						
28						
29						
30	7.5				Y	
31	7.4				Y	
No = N = Excursion					Total N's	0

County: Josephine Agency: 5

Entry Point
A

PWS ID 4100971

Cave Junction, City of

Sample Period:
Month/Year Jan. 2024

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.3

Print Name: Steven Bethke
Signature: Steven Bethke
Date: 2-7-24

Send to DWP within 10 days after end of sampling period
DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp