

Lead & Copper Rule Corrosion Control

AUTHORITY

Day	Ph	Alk	Phos	Sili	Y/N	<< Have Minimums Been Met for this day
1						
2	7.4				Y	
3	7.5				Y	
4	7.5				Y	
5	7.5				Y	
6						
7						
8						
9	7.4				Y	
10	7.4				Y	
11	7.5				Y	Month/Year
12	7.5				Y	
13						
14						
15						
16	7.5				Y	
17	7.4				Y	
18	7.4				Y	
19	7.4				Y	
20	7.5				Y	
21						
22	7.5				Y	
23	7.4				Y	
24	7.4				Y	
25	7.5				Y	
26	7.5				Y	
27	7.5				Y	
28						
29	7.6				Y	
30						
31	7.5				Y	
No = N = Excursion					Total N's	0

County: Josephine Agency: 5
Entry Point
A
PWS ID 4100971
Cave Junction, City of

Sample Period:
 Month/Year May 2022

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An excursion is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
 Parameter(s) as set by State:**

pH 7.3

Print Name: Steve Bethke
 Signature: *Steve Bethke*
 Date: 6-1-22

Send to DWP within 10 days after end of sampling period
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp