

AUTHORITY

## Lead & Copper Rule Corrosion Control

Day	Ph	Alk	Phos	Sili	Y/N	<< Have Minimums Been Met for this day
1						
2	7.5				Y	
3	7.5				Y	
4	7.5				Y	
5	7.6				Y	
6	7.6				Y	
7	7.6				Y	
8	7.5				Y	
9	7.5				Y	
10	7.5				Y	
11	7.5				Y	
12	7.5				Y	
13	7.5				Y	
14	7.3				Y	
15						
16	7.6				Y	
17	7.5				Y	
18	7.6				Y	
19	7.5				Y	
20	7.6				Y	
21	7.5				Y	
22						
23						
24	7.5				Y	
25						
26						
27	7.5				Y	
28	7.5				Y	
29						
30						
31	7.5				Y	
No = N = Excursion					<b>Total N's</b>	0

County: Josephine	Agency: 5
<b>Entry Point</b>	
<b>A</b>	
<b>PWS ID 4100971</b>	
<b>Cave Junction, City of</b>	
Sample Period:	
Month/Year Oct. 2022	

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An excursion is any day in which the water quality parameter(s) fall below the minimum set by the State.

<b>Reference</b>
<b>Minimum Water Quality Parameter(s) as set by State:</b>
pH <span style="border: 1px solid black; padding: 2px 10px;">7.3</span>

Print Name: Steven Bethke  
 Signature: Steven Bethke  
 Date: 11-2-22

Send to DWP within 10 days after end of sampling period  
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp